

Vehicle Speed Report Summary

Location: Henderson Rd, Between Wilshire Dr & Kelly Ln

Count Direction: Northbound / Southbound

Date Range: 2/22/2022 to 2/23/2022

Site Code: YB3601

	Speed Range (mph)																	Total
	0 - 10	10 - 15	15 - 20	20 - 25	25 - 30	30 - 35	35 - 40	40 - 45	45 - 50	50 - 55	55 - 60	60 - 65	65 - 70	70 - 75	75 - 80	80 - 85	85 +	Volume
Study Total																		
Northbound	7	26	55	101	171	51	10	2	0	0	0	0	0	0	0	0	0	423
Percent	1.7%	6.1%	13.0%	23.9%	40.4%	12.1%	2.4%	0.5%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	100%
Southbound	7	26	41	100	148	57	17	4	0	0	0	0	0	0	0	0	0	400
Percent	1.8%	6.5%	10.3%	25.0%	37.0%	14.3%	4.3%	1.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	100%
Total	14	52	96	201	319	108	27	6	0	0	0	0	0	0	0	0	0	823
Percent	1.7%	6.3%	11.7%	24.4%	38.8%	13.1%	3.3%	0.7%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	100%

Total Study Percentile Speed Summary				Total Study Speed Statistics			
Northbound				Northbound			
50th Percentile (Median)	25.6	mph		Mean (Average) Speed	24.6	mph	
85th Percentile	30.0	mph		10 mph Pace	20.8 - 30.8	mph	
95th Percentile	33.4	mph		Percent in Pace	66.0	%	
Southbound				Southbound			
50th Percentile (Median)	26.2	mph		Mean (Average) Speed	25.3	mph	
85th Percentile	31.1	mph		10 mph Pace	20.9 - 30.9	mph	
95th Percentile	35.1	mph		Percent in Pace	63.8	%	

Location: Henderson Rd, Between Wilshire Dr & Kelly Ln
 Date Range: 2/22/2022 to 2/23/2022
 Site Code: YB3601



Tuesday, February 22, 2022
 Northbound

Time	Speed Range (mph)																	Total Volume
	0 - 10	10 - 15	15 - 20	20 - 25	25 - 30	30 - 35	35 - 40	40 - 45	45 - 50	50 - 55	55 - 60	60 - 65	65 - 70	70 - 75	75 - 80	80 - 85	85 +	
12:00 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
1:00 AM	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	1
2:00 AM	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	1
3:00 AM	0	0	0	0	2	1	0	0	0	0	0	0	0	0	0	0	0	3
4:00 AM	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	1
5:00 AM	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	1
6:00 AM	0	0	0	0	4	1	0	0	0	0	0	0	0	0	0	0	0	5
7:00 AM	0	0	0	3	9	3	0	0	0	0	0	0	0	0	0	0	0	15
8:00 AM	0	0	3	2	7	2	0	0	0	0	0	0	0	0	0	0	0	14
9:00 AM	0	1	4	6	2	0	0	0	0	0	0	0	0	0	0	0	0	13
10:00 AM	0	1	1	2	4	5	0	0	0	0	0	0	0	0	0	0	0	13
11:00 AM	0	1	0	2	4	1	0	1	0	0	0	0	0	0	0	0	0	9
12:00 PM	1	1	3	2	6	4	1	0	0	0	0	0	0	0	0	0	0	18
1:00 PM	0	0	1	7	6	2	0	0	0	0	0	0	0	0	0	0	0	16
2:00 PM	1	1	2	5	6	1	0	0	0	0	0	0	0	0	0	0	0	16
3:00 PM	0	3	3	2	5	0	0	0	0	0	0	0	0	0	0	0	0	13
4:00 PM	1	0	3	7	3	1	1	0	0	0	0	0	0	0	0	0	0	16
5:00 PM	0	1	3	5	1	0	1	0	0	0	0	0	0	0	0	0	0	11
6:00 PM	0	1	6	4	5	1	0	0	0	0	0	0	0	0	0	0	0	17
7:00 PM	0	0	2	3	4	0	0	0	0	0	0	0	0	0	0	0	0	9
8:00 PM	0	0	0	0	4	0	0	0	0	0	0	0	0	0	0	0	0	4
9:00 PM	0	0	0	1	1	1	0	0	0	0	0	0	0	0	0	0	0	3
10:00 PM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
11:00 PM	0	0	0	0	2	0	0	0	0	0	0	0	0	0	0	0	0	2
Total	3	10	31	51	79	23	3	1	0	0	0	0	0	0	0	0	0	201
Percent	1.5%	5.0%	15.4%	25.4%	39.3%	11.4%	1.5%	0.5%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	

Daily Percentile Speed Summary			Speed Statistics		
50th Percentile (Median)	25.4	mph	Mean (Average) Speed	24.4	mph
85th Percentile	29.8	mph	10 mph Pace	20.1 - 30.1	mph
95th Percentile	32.7	mph	Percent in Pace	65.2	%

Location: Henderson Rd, Between Wilshire Dr & Kelly Ln
 Date Range: 2/22/2022 to 2/23/2022
 Site Code: YB3601

Tuesday, February 22, 2022
 Southbound

Time	Speed Range (mph)																	Total Volume
	0 - 10	10 - 15	15 - 20	20 - 25	25 - 30	30 - 35	35 - 40	40 - 45	45 - 50	50 - 55	55 - 60	60 - 65	65 - 70	70 - 75	75 - 80	80 - 85	85 +	
12:00 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
1:00 AM	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
2:00 AM	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	1
3:00 AM	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	1
4:00 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
5:00 AM	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	1
6:00 AM	0	0	0	2	0	0	0	0	0	0	0	0	0	0	0	0	0	2
7:00 AM	0	0	0	3	3	1	0	1	0	0	0	0	0	0	0	0	0	8
8:00 AM	0	0	1	2	5	1	0	0	0	0	0	0	0	0	0	0	0	9
9:00 AM	0	1	0	0	4	0	1	0	0	0	0	0	0	0	0	0	0	6
10:00 AM	2	2	5	5	9	1	3	0	0	0	0	0	0	0	0	0	0	27
11:00 AM	2	1	0	2	8	3	1	0	0	0	0	0	0	0	0	0	0	17
12:00 PM	1	0	1	9	5	5	0	0	0	0	0	0	0	0	0	0	0	21
1:00 PM	0	0	1	6	8	2	1	0	0	0	0	0	0	0	0	0	0	18
2:00 PM	0	2	2	8	2	2	0	0	0	0	0	0	0	0	0	0	0	16
3:00 PM	0	2	0	0	8	4	0	0	0	0	0	0	0	0	0	0	0	14
4:00 PM	1	3	3	2	5	2	0	0	0	0	0	0	0	0	0	0	0	16
5:00 PM	0	1	5	4	9	0	0	0	0	0	0	0	0	0	0	0	0	19
6:00 PM	0	0	1	3	3	1	0	1	0	0	0	0	0	0	0	0	0	9
7:00 PM	0	0	3	0	2	1	1	0	0	0	0	0	0	0	0	0	0	7
8:00 PM	0	1	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	2
9:00 PM	0	1	0	1	0	0	1	0	0	0	0	0	0	0	0	0	0	3
10:00 PM	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	1
11:00 PM	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	1
Total	6	15	22	49	74	24	8	2	0	0	0	0	0	0	0	0	0	200
Percent	3.0%	7.5%	11.0%	24.5%	37.0%	12.0%	4.0%	1.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	

Daily Percentile Speed Summary			Speed Statistics		
50th Percentile (Median)	25.7	mph	Mean (Average) Speed	24.7	mph
85th Percentile	30.4	mph	10 mph Pace	21.3 - 31.3	mph
95th Percentile	35.2	mph	Percent in Pace	63	%

Location: Henderson Rd, Between Wilshire Dr & Kelly Ln
 Date Range: 2/22/2022 to 2/23/2022
 Site Code: YB3601

Wednesday, February 23, 2022
 Northbound

Time	Speed Range (mph)																	Total Volume
	0 - 10	10 - 15	15 - 20	20 - 25	25 - 30	30 - 35	35 - 40	40 - 45	45 - 50	50 - 55	55 - 60	60 - 65	65 - 70	70 - 75	75 - 80	80 - 85	85 +	
12:00 AM	1	0	2	0	0	0	0	0	0	0	0	0	0	0	0	0	0	3
1:00 AM	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
2:00 AM	0	0	0	0	2	0	0	0	0	0	0	0	0	0	0	0	0	2
3:00 AM	0	0	0	0	2	1	0	0	0	0	0	0	0	0	0	0	0	3
4:00 AM	0	0	0	0	2	0	0	0	0	0	0	0	0	0	0	0	0	2
5:00 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
6:00 AM	0	0	0	1	2	0	0	0	0	0	0	0	0	0	0	0	0	3
7:00 AM	0	0	0	5	5	3	0	0	0	0	0	0	0	0	0	0	0	13
8:00 AM	0	2	1	4	11	3	0	0	0	0	0	0	0	0	0	0	0	21
9:00 AM	1	3	2	3	3	5	0	0	0	0	0	0	0	0	0	0	0	17
10:00 AM	1	0	2	2	4	2	1	0	0	0	0	0	0	0	0	0	0	12
11:00 AM	1	1	2	10	9	0	0	0	0	0	0	0	0	0	0	0	0	23
12:00 PM	0	0	1	3	4	2	0	0	0	0	0	0	0	0	0	0	0	10
1:00 PM	0	3	6	2	4	2	2	0	0	0	0	0	0	0	0	0	0	19
2:00 PM	0	2	2	2	8	1	1	0	0	0	0	0	0	0	0	0	0	16
3:00 PM	0	1	0	1	9	3	0	0	0	0	0	0	0	0	0	0	0	14
4:00 PM	0	1	1	5	12	2	1	1	0	0	0	0	0	0	0	0	0	23
5:00 PM	0	1	0	1	5	1	0	0	0	0	0	0	0	0	0	0	0	8
6:00 PM	0	1	2	5	1	0	0	0	0	0	0	0	0	0	0	0	0	9
7:00 PM	0	0	1	1	6	1	0	0	0	0	0	0	0	0	0	0	0	9
8:00 PM	0	1	1	3	2	0	1	0	0	0	0	0	0	0	0	0	0	8
9:00 PM	0	0	0	0	1	1	0	0	0	0	0	0	0	0	0	0	0	2
10:00 PM	0	0	0	2	0	1	1	0	0	0	0	0	0	0	0	0	0	4
11:00 PM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Total	4	16	24	50	92	28	7	1	0	0	0	0	0	0	0	0	0	222
Percent	1.8%	7.2%	10.8%	22.5%	41.4%	12.6%	3.2%	0.5%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	

Daily Percentile Speed Summary			Speed Statistics		
50th Percentile (Median)	25.6	mph	Mean (Average) Speed	24.7	mph
85th Percentile	30.2	mph	10 mph Pace	20.8 - 30.8	mph
95th Percentile	34.0	mph	Percent in Pace	66.7	%

Location: Henderson Rd, Between Wilshire Dr & Kelly Ln
 Date Range: 2/22/2022 to 2/23/2022
 Site Code: YB3601

Wednesday, February 23, 2022
 Southbound

Time	Speed Range (mph)																	Total Volume
	0 - 10	10 - 15	15 - 20	20 - 25	25 - 30	30 - 35	35 - 40	40 - 45	45 - 50	50 - 55	55 - 60	60 - 65	65 - 70	70 - 75	75 - 80	80 - 85	85 +	
12:00 AM	0	0	1	1	0	0	0	0	0	0	0	0	0	0	0	0	0	2
1:00 AM	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	1
2:00 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
3:00 AM	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	1
4:00 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
5:00 AM	0	0	0	1	1	0	0	0	0	0	0	0	0	0	0	0	0	2
6:00 AM	0	0	0	0	2	0	0	0	0	0	0	0	0	0	0	0	0	2
7:00 AM	0	0	0	3	5	1	0	1	0	0	0	0	0	0	0	0	0	10
8:00 AM	0	0	1	3	4	0	0	0	0	0	0	0	0	0	0	0	0	8
9:00 AM	0	0	0	2	3	1	1	0	0	0	0	0	0	0	0	0	0	7
10:00 AM	0	1	2	1	7	3	0	0	0	0	0	0	0	0	0	0	0	14
11:00 AM	0	2	2	3	5	2	1	0	0	0	0	0	0	0	0	0	0	15
12:00 PM	0	0	1	0	3	6	2	1	0	0	0	0	0	0	0	0	0	13
1:00 PM	0	2	4	4	8	2	2	0	0	0	0	0	0	0	0	0	0	22
2:00 PM	0	1	1	6	6	2	0	0	0	0	0	0	0	0	0	0	0	16
3:00 PM	0	0	1	2	5	6	2	0	0	0	0	0	0	0	0	0	0	16
4:00 PM	0	1	2	7	5	4	0	0	0	0	0	0	0	0	0	0	0	19
5:00 PM	0	1	0	7	8	2	0	0	0	0	0	0	0	0	0	0	0	18
6:00 PM	1	1	0	2	5	1	0	0	0	0	0	0	0	0	0	0	0	10
7:00 PM	0	0	2	2	0	0	0	0	0	0	0	0	0	0	0	0	0	4
8:00 PM	0	1	0	3	2	1	0	0	0	0	0	0	0	0	0	0	0	7
9:00 PM	0	1	2	0	4	1	0	0	0	0	0	0	0	0	0	0	0	8
10:00 PM	0	0	0	4	1	0	0	0	0	0	0	0	0	0	0	0	0	5
11:00 PM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Total	1	11	19	51	74	33	9	2	0	0	0	0	0	0	0	0	0	200
Percent	0.5%	5.5%	9.5%	25.5%	37.0%	16.5%	4.5%	1.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	

Daily Percentile Speed Summary			Speed Statistics		
50th Percentile (Median)	26.3	mph	Mean (Average) Speed	25.8	mph
85th Percentile	31.8	mph	10 mph Pace	22.3 - 32.3	mph
95th Percentile	35.1	mph	Percent in Pace	65.5	%

Location: Henderson Rd, Between Wilshire Dr & Kelly Ln
 Date Range: 2/22/2022 to 2/23/2022
 Site Code: YB3601

Total Study Average
Northbound

Time	Speed Range (mph)																	Total Volume
	0 - 10	10 - 15	15 - 20	20 - 25	25 - 30	30 - 35	35 - 40	40 - 45	45 - 50	50 - 55	55 - 60	60 - 65	65 - 70	70 - 75	75 - 80	80 - 85	85 +	
12:00 AM	1	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	2
1:00 AM	0	0	1	0	1	0	0	0	0	0	0	0	0	0	0	0	0	2
2:00 AM	0	0	0	0	2	0	0	0	0	0	0	0	0	0	0	0	0	2
3:00 AM	0	0	0	0	2	1	0	0	0	0	0	0	0	0	0	0	0	3
4:00 AM	0	0	0	0	2	0	0	0	0	0	0	0	0	0	0	0	0	2
5:00 AM	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	1
6:00 AM	0	0	0	1	3	1	0	0	0	0	0	0	0	0	0	0	0	5
7:00 AM	0	0	0	4	7	3	0	0	0	0	0	0	0	0	0	0	0	14
8:00 AM	0	1	2	3	9	3	0	0	0	0	0	0	0	0	0	0	0	18
9:00 AM	1	2	3	5	3	3	0	0	0	0	0	0	0	0	0	0	0	17
10:00 AM	1	1	2	2	4	4	1	0	0	0	0	0	0	0	0	0	0	15
11:00 AM	1	1	1	6	7	1	0	1	0	0	0	0	0	0	0	0	0	18
12:00 PM	1	1	2	3	5	3	1	0	0	0	0	0	0	0	0	0	0	16
1:00 PM	0	2	4	5	5	2	1	0	0	0	0	0	0	0	0	0	0	19
2:00 PM	1	2	2	4	7	1	1	0	0	0	0	0	0	0	0	0	0	18
3:00 PM	0	2	2	2	7	2	0	0	0	0	0	0	0	0	0	0	0	15
4:00 PM	1	1	2	6	8	2	1	1	0	0	0	0	0	0	0	0	0	22
5:00 PM	0	1	2	3	3	1	1	0	0	0	0	0	0	0	0	0	0	11
6:00 PM	0	1	4	5	3	1	0	0	0	0	0	0	0	0	0	0	0	14
7:00 PM	0	0	2	2	5	1	0	0	0	0	0	0	0	0	0	0	0	10
8:00 PM	0	1	1	2	3	0	1	0	0	0	0	0	0	0	0	0	0	8
9:00 PM	0	0	0	1	1	1	0	0	0	0	0	0	0	0	0	0	0	3
10:00 PM	0	0	0	1	0	1	1	0	0	0	0	0	0	0	0	0	0	3
11:00 PM	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	1
Total	7	16	31	55	89	31	8	2	0	0	0	0	0	0	0	0	0	239
Percent	2.9%	6.7%	13.0%	23.0%	37.2%	13.0%	3.3%	0.8%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	

Note: Average only considered on days with 24-hours of data.

Total Study Percentile Speed Summary			Total Study Speed Statistics		
50th Percentile (Median)	25.6	mph	Mean (Average) Speed	24.6	mph
85th Percentile	30.0	mph	10 mph Pace	20.8 - 30.8	mph
95th Percentile	33.4	mph	Percent in Pace	66.0	%

Location: Henderson Rd, Between Wilshire Dr & Kelly Ln
 Date Range: 2/22/2022 to 2/23/2022
 Site Code: YB3601

Total Study Average
Southbound

Time	Speed Range (mph)																	Total Volume
	0 - 10	10 - 15	15 - 20	20 - 25	25 - 30	30 - 35	35 - 40	40 - 45	45 - 50	50 - 55	55 - 60	60 - 65	65 - 70	70 - 75	75 - 80	80 - 85	85 +	
12:00 AM	0	0	1	1	0	0	0	0	0	0	0	0	0	0	0	0	0	2
1:00 AM	0	1	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	2
2:00 AM	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	1
3:00 AM	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	1
4:00 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
5:00 AM	0	0	0	1	1	0	0	0	0	0	0	0	0	0	0	0	0	2
6:00 AM	0	0	0	1	1	0	0	0	0	0	0	0	0	0	0	0	0	2
7:00 AM	0	0	0	3	4	1	0	1	0	0	0	0	0	0	0	0	0	9
8:00 AM	0	0	1	3	5	1	0	0	0	0	0	0	0	0	0	0	0	10
9:00 AM	0	1	0	1	4	1	1	0	0	0	0	0	0	0	0	0	0	8
10:00 AM	1	2	4	3	8	2	2	0	0	0	0	0	0	0	0	0	0	22
11:00 AM	1	2	1	3	7	3	1	0	0	0	0	0	0	0	0	0	0	18
12:00 PM	1	0	1	5	4	6	1	1	0	0	0	0	0	0	0	0	0	19
1:00 PM	0	1	3	5	8	2	2	0	0	0	0	0	0	0	0	0	0	21
2:00 PM	0	2	2	7	4	2	0	0	0	0	0	0	0	0	0	0	0	17
3:00 PM	0	1	1	1	7	5	1	0	0	0	0	0	0	0	0	0	0	16
4:00 PM	1	2	3	5	5	3	0	0	0	0	0	0	0	0	0	0	0	19
5:00 PM	0	1	3	6	9	1	0	0	0	0	0	0	0	0	0	0	0	20
6:00 PM	1	1	1	3	4	1	0	1	0	0	0	0	0	0	0	0	0	12
7:00 PM	0	0	3	1	1	1	1	0	0	0	0	0	0	0	0	0	0	7
8:00 PM	0	1	0	2	2	1	0	0	0	0	0	0	0	0	0	0	0	6
9:00 PM	0	1	1	1	2	1	1	0	0	0	0	0	0	0	0	0	0	7
10:00 PM	0	0	0	3	1	0	0	0	0	0	0	0	0	0	0	0	0	4
11:00 PM	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	1
Total	5	16	25	56	78	32	11	3	0	0	0	0	0	0	0	0	0	226
Percent	2.2%	7.1%	11.1%	24.8%	34.5%	14.2%	4.9%	1.3%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	

Note: Average only considered on days with 24-hours of data.

Total Study Percentile Speed Summary			Total Study Speed Statistics		
50th Percentile (Median)	26.2	mph	Mean (Average) Speed	25.3	mph
85th Percentile	31.1	mph	10 mph Pace	20.9 - 30.9	mph
95th Percentile	35.1	mph	Percent in Pace	63.8	%