

Vehicle Speed Report Summary

Location: Henderson Rd, Between Kelly Ln & .17 Miles N-O Kelly Ln

Count Direction: Northbound / Southbound

Date Range: 2/22/2022 to 2/23/2022

Site Code: YB3601

	Speed Range (mph)																	Total
	0 - 10	10 - 15	15 - 20	20 - 25	25 - 30	30 - 35	35 - 40	40 - 45	45 - 50	50 - 55	55 - 60	60 - 65	65 - 70	70 - 75	75 - 80	80 - 85	85 +	Volume
Study Total																		
Northbound	13	38	91	195	125	26	1	0	0	0	0	0	0	0	0	0	0	489
Percent	2.7%	7.8%	18.6%	39.9%	25.6%	5.3%	0.2%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	100%
Southbound	13	37	105	172	99	22	6	0	0	0	0	0	0	0	0	0	0	454
Percent	2.9%	8.1%	23.1%	37.9%	21.8%	4.8%	1.3%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	100%
Total	26	75	196	367	224	48	7	0	0	0	0	0	0	0	0	0	0	943
Percent	2.8%	8.0%	20.8%	38.9%	23.8%	5.1%	0.7%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	100%

Total Study Percentile Speed Summary				Total Study Speed Statistics			
Northbound				Northbound			
50th Percentile (Median)		22.7	mph	Mean (Average) Speed		22.2	mph
85th Percentile		27.1	mph	10 mph Pace		17.6 - 27.6	mph
95th Percentile		30.2	mph	Percent in Pace		70.8	%
Southbound				Southbound			
50th Percentile (Median)		21.8	mph	Mean (Average) Speed		21.9	mph
85th Percentile		27.2	mph	10 mph Pace		17.4 - 27.4	mph
95th Percentile		30.6	mph	Percent in Pace		70.0	%

Location: Henderson Rd, Between Kelly Ln & .17 Miles N-O Kelly Ln
Date Range: 2/22/2022 to 2/23/2022
Site Code: YB3601

Tuesday, February 22, 2022
Northbound

Time	Speed Range (mph)																	Total Volume
	0 - 10	10 - 15	15 - 20	20 - 25	25 - 30	30 - 35	35 - 40	40 - 45	45 - 50	50 - 55	55 - 60	60 - 65	65 - 70	70 - 75	75 - 80	80 - 85	85 +	
12:00 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
1:00 AM	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	1
2:00 AM	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	1
3:00 AM	0	0	0	0	1	1	0	0	0	0	0	0	0	0	0	0	0	2
4:00 AM	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	1
5:00 AM	0	0	0	2	0	0	0	0	0	0	0	0	0	0	0	0	0	2
6:00 AM	0	0	1	3	3	1	0	0	0	0	0	0	0	0	0	0	0	8
7:00 AM	0	1	2	8	9	0	0	0	0	0	0	0	0	0	0	0	0	20
8:00 AM	1	0	2	11	5	1	0	0	0	0	0	0	0	0	0	0	0	20
9:00 AM	0	0	4	7	3	0	0	0	0	0	0	0	0	0	0	0	0	14
10:00 AM	0	2	2	2	7	3	0	0	0	0	0	0	0	0	0	0	0	16
11:00 AM	1	2	8	4	0	2	0	0	0	0	0	0	0	0	0	0	0	17
12:00 PM	2	1	3	8	7	2	0	0	0	0	0	0	0	0	0	0	0	23
1:00 PM	0	1	3	6	5	1	0	0	0	0	0	0	0	0	0	0	0	16
2:00 PM	0	0	4	9	6	0	0	0	0	0	0	0	0	0	0	0	0	19
3:00 PM	1	1	5	3	4	1	0	0	0	0	0	0	0	0	0	0	0	15
4:00 PM	0	2	6	3	2	1	0	0	0	0	0	0	0	0	0	0	0	14
5:00 PM	0	0	3	7	1	1	0	0	0	0	0	0	0	0	0	0	0	12
6:00 PM	0	1	1	9	3	1	0	0	0	0	0	0	0	0	0	0	0	15
7:00 PM	0	1	1	4	0	0	0	0	0	0	0	0	0	0	0	0	0	6
8:00 PM	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	1
9:00 PM	0	0	0	1	3	0	0	0	0	0	0	0	0	0	0	0	0	4
10:00 PM	0	0	0	2	0	0	0	0	0	0	0	0	0	0	0	0	0	2
11:00 PM	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Total	5	12	45	91	62	15	0	0	0	0	0	0	0	0	0	0	0	230
Percent	2.2%	5.2%	19.6%	39.6%	27.0%	6.5%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	

Daily Percentile Speed Summary			Speed Statistics		
50th Percentile (Median)	22.8	mph	Mean (Average) Speed	22.6	mph
85th Percentile	27.3	mph	10 mph Pace	17.4 - 27.4	mph
95th Percentile	30.5	mph	Percent in Pace	72.6	%

Location: Henderson Rd, Between Kelly Ln & .17 Miles N-O Kelly Ln
Date Range: 2/22/2022 to 2/23/2022
Site Code: YB3601

Tuesday, February 22, 2022
Southbound

Time	Speed Range (mph)																	Total Volume
	0 - 10	10 - 15	15 - 20	20 - 25	25 - 30	30 - 35	35 - 40	40 - 45	45 - 50	50 - 55	55 - 60	60 - 65	65 - 70	70 - 75	75 - 80	80 - 85	85 +	
12:00 AM	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
1:00 AM	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
2:00 AM	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
3:00 AM	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	1
4:00 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
5:00 AM	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
6:00 AM	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
7:00 AM	0	1	2	2	2	0	1	0	0	0	0	0	0	0	0	0	0	8
8:00 AM	0	2	3	2	3	0	0	0	0	0	0	0	0	0	0	0	0	10
9:00 AM	0	1	0	8	3	1	0	0	0	0	0	0	0	0	0	0	0	13
10:00 AM	2	3	5	12	2	2	0	0	0	0	0	0	0	0	0	0	0	26
11:00 AM	1	2	1	6	7	1	0	0	0	0	0	0	0	0	0	0	0	18
12:00 PM	1	1	13	7	8	1	0	0	0	0	0	0	0	0	0	0	0	31
1:00 PM	3	0	3	8	7	0	0	0	0	0	0	0	0	0	0	0	0	21
2:00 PM	1	1	7	5	3	1	0	0	0	0	0	0	0	0	0	0	0	18
3:00 PM	0	1	4	5	7	0	0	0	0	0	0	0	0	0	0	0	0	17
4:00 PM	0	1	3	3	5	0	0	0	0	0	0	0	0	0	0	0	0	12
5:00 PM	0	2	4	12	3	1	0	0	0	0	0	0	0	0	0	0	0	22
6:00 PM	0	1	2	5	1	0	0	0	0	0	0	0	0	0	0	0	0	9
7:00 PM	0	0	3	3	3	0	0	0	0	0	0	0	0	0	0	0	0	9
8:00 PM	0	0	1	0	0	1	0	0	0	0	0	0	0	0	0	0	0	2
9:00 PM	0	0	0	1	1	0	0	0	0	0	0	0	0	0	0	0	0	2
10:00 PM	0	0	0	2	0	0	0	0	0	0	0	0	0	0	0	0	0	2
11:00 PM	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Total	9	16	55	82	55	9	1	0	0	0	0	0	0	0	0	0	0	227
Percent	4.0%	7.0%	24.2%	36.1%	24.2%	4.0%	0.4%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	

Daily Percentile Speed Summary			Speed Statistics		
50th Percentile (Median)	21.6	mph	Mean (Average) Speed	21.6	mph
85th Percentile	27.0	mph	10 mph Pace	17.4 - 27.4	mph
95th Percentile	29.8	mph	Percent in Pace	70.93	%

Location: Henderson Rd, Between Kelly Ln & .17 Miles N-O Kelly Ln
 Date Range: 2/22/2022 to 2/23/2022
 Site Code: YB3601

Wednesday, February 23, 2022
 Northbound

Time	Speed Range (mph)																	Total Volume
	0 - 10	10 - 15	15 - 20	20 - 25	25 - 30	30 - 35	35 - 40	40 - 45	45 - 50	50 - 55	55 - 60	60 - 65	65 - 70	70 - 75	75 - 80	80 - 85	85 +	
12:00 AM	0	0	1	2	0	0	0	0	0	0	0	0	0	0	0	0	0	3
1:00 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
2:00 AM	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	1
3:00 AM	0	0	0	0	0	2	0	0	0	0	0	0	0	0	0	0	0	2
4:00 AM	0	0	0	2	0	0	0	0	0	0	0	0	0	0	0	0	0	2
5:00 AM	0	0	1	2	0	0	0	0	0	0	0	0	0	0	0	0	0	3
6:00 AM	0	0	4	4	0	0	0	0	0	0	0	0	0	0	0	0	0	8
7:00 AM	0	0	2	8	6	0	1	0	0	0	0	0	0	0	0	0	0	17
8:00 AM	0	2	6	5	9	2	0	0	0	0	0	0	0	0	0	0	0	24
9:00 AM	1	0	3	7	6	3	0	0	0	0	0	0	0	0	0	0	0	20
10:00 AM	0	1	1	4	7	2	0	0	0	0	0	0	0	0	0	0	0	15
11:00 AM	2	6	7	13	3	0	0	0	0	0	0	0	0	0	0	0	0	31
12:00 PM	0	0	0	7	6	0	0	0	0	0	0	0	0	0	0	0	0	13
1:00 PM	1	2	6	7	2	0	0	0	0	0	0	0	0	0	0	0	0	18
2:00 PM	2	6	1	5	5	0	0	0	0	0	0	0	0	0	0	0	0	19
3:00 PM	0	1	1	12	4	0	0	0	0	0	0	0	0	0	0	0	0	18
4:00 PM	0	2	1	11	8	2	0	0	0	0	0	0	0	0	0	0	0	24
5:00 PM	0	2	4	6	1	0	0	0	0	0	0	0	0	0	0	0	0	13
6:00 PM	0	4	3	4	1	0	0	0	0	0	0	0	0	0	0	0	0	12
7:00 PM	0	0	0	0	2	0	0	0	0	0	0	0	0	0	0	0	0	2
8:00 PM	1	0	3	2	1	0	0	0	0	0	0	0	0	0	0	0	0	7
9:00 PM	0	0	2	1	0	0	0	0	0	0	0	0	0	0	0	0	0	3
10:00 PM	1	0	0	2	1	0	0	0	0	0	0	0	0	0	0	0	0	4
11:00 PM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Total	8	26	46	104	63	11	1	0	0	0	0	0	0	0	0	0	0	259
Percent	3.1%	10.0%	17.8%	40.2%	24.3%	4.2%	0.4%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	

Daily Percentile Speed Summary			Speed Statistics		
50th Percentile (Median)	22.3	mph	Mean (Average) Speed	21.9	mph
85th Percentile	27.0	mph	10 mph Pace	17.9 - 27.9	mph
95th Percentile	29.8	mph	Percent in Pace	69.9	%

Location: Henderson Rd, Between Kelly Ln & .17 Miles N-O Kelly Ln
 Date Range: 2/22/2022 to 2/23/2022
 Site Code: YB3601

Wednesday, February 23, 2022
 Southbound

Time	Speed Range (mph)																	Total Volume
	0 - 10	10 - 15	15 - 20	20 - 25	25 - 30	30 - 35	35 - 40	40 - 45	45 - 50	50 - 55	55 - 60	60 - 65	65 - 70	70 - 75	75 - 80	80 - 85	85 +	
12:00 AM	0	1	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	2
1:00 AM	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	1
2:00 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
3:00 AM	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	1
4:00 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
5:00 AM	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
6:00 AM	0	0	1	2	0	0	0	0	0	0	0	0	0	0	0	0	0	3
7:00 AM	0	1	3	6	1	0	1	0	0	0	0	0	0	0	0	0	0	12
8:00 AM	0	2	3	7	2	1	0	0	0	0	0	0	0	0	0	0	0	15
9:00 AM	0	0	1	4	1	1	0	0	0	0	0	0	0	0	0	0	0	7
10:00 AM	0	0	4	5	7	0	0	0	0	0	0	0	0	0	0	0	0	16
11:00 AM	1	1	3	6	2	1	0	0	0	0	0	0	0	0	0	0	0	14
12:00 PM	0	0	2	3	5	3	1	0	0	0	0	0	0	0	0	0	0	14
1:00 PM	2	0	4	10	4	0	3	0	0	0	0	0	0	0	0	0	0	23
2:00 PM	0	5	5	6	3	1	0	0	0	0	0	0	0	0	0	0	0	20
3:00 PM	0	1	9	5	4	2	0	0	0	0	0	0	0	0	0	0	0	21
4:00 PM	0	0	4	12	6	1	0	0	0	0	0	0	0	0	0	0	0	23
5:00 PM	0	5	0	8	7	1	0	0	0	0	0	0	0	0	0	0	0	21
6:00 PM	0	1	2	4	2	0	0	0	0	0	0	0	0	0	0	0	0	9
7:00 PM	0	2	3	1	0	0	0	0	0	0	0	0	0	0	0	0	0	6
8:00 PM	0	1	1	4	0	0	0	0	0	0	0	0	0	0	0	0	0	6
9:00 PM	0	1	3	3	0	0	0	0	0	0	0	0	0	0	0	0	0	7
10:00 PM	0	0	0	4	0	0	0	0	0	0	0	0	0	0	0	0	0	4
11:00 PM	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Total	4	21	50	90	44	13	5	0	0	0	0	0	0	0	0	0	0	227
Percent	1.8%	9.3%	22.0%	39.6%	19.4%	5.7%	2.2%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	

Daily Percentile Speed Summary			Speed Statistics		
50th Percentile (Median)	22.0	mph	Mean (Average) Speed	22.1	mph
85th Percentile	27.5	mph	10 mph Pace	17.9 - 27.9	mph
95th Percentile	31.6	mph	Percent in Pace	69.6	%

Location: Henderson Rd, Between Kelly Ln & .17 Miles N-O Kelly Ln
 Date Range: 2/22/2022 to 2/23/2022
 Site Code: YB3601

Total Study Average
Northbound

Time	Speed Range (mph)																	Total Volume
	0 - 10	10 - 15	15 - 20	20 - 25	25 - 30	30 - 35	35 - 40	40 - 45	45 - 50	50 - 55	55 - 60	60 - 65	65 - 70	70 - 75	75 - 80	80 - 85	85 +	
12:00 AM	0	0	1	1	0	0	0	0	0	0	0	0	0	0	0	0	0	2
1:00 AM	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	1
2:00 AM	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	1
3:00 AM	0	0	0	0	1	2	0	0	0	0	0	0	0	0	0	0	0	3
4:00 AM	0	0	0	1	1	0	0	0	0	0	0	0	0	0	0	0	0	2
5:00 AM	0	0	1	2	0	0	0	0	0	0	0	0	0	0	0	0	0	3
6:00 AM	0	0	3	4	2	1	0	0	0	0	0	0	0	0	0	0	0	10
7:00 AM	0	1	2	8	8	0	1	0	0	0	0	0	0	0	0	0	0	20
8:00 AM	1	1	4	8	7	2	0	0	0	0	0	0	0	0	0	0	0	23
9:00 AM	1	0	4	7	5	2	0	0	0	0	0	0	0	0	0	0	0	19
10:00 AM	0	2	2	3	7	3	0	0	0	0	0	0	0	0	0	0	0	17
11:00 AM	2	4	8	9	2	1	0	0	0	0	0	0	0	0	0	0	0	26
12:00 PM	1	1	2	8	7	1	0	0	0	0	0	0	0	0	0	0	0	20
1:00 PM	1	2	5	7	4	1	0	0	0	0	0	0	0	0	0	0	0	20
2:00 PM	1	3	3	7	6	0	0	0	0	0	0	0	0	0	0	0	0	20
3:00 PM	1	1	3	8	4	1	0	0	0	0	0	0	0	0	0	0	0	18
4:00 PM	0	2	4	7	5	2	0	0	0	0	0	0	0	0	0	0	0	20
5:00 PM	0	1	4	7	1	1	0	0	0	0	0	0	0	0	0	0	0	14
6:00 PM	0	3	2	7	2	1	0	0	0	0	0	0	0	0	0	0	0	15
7:00 PM	0	1	1	2	1	0	0	0	0	0	0	0	0	0	0	0	0	5
8:00 PM	1	0	2	1	1	0	0	0	0	0	0	0	0	0	0	0	0	5
9:00 PM	0	0	1	1	2	0	0	0	0	0	0	0	0	0	0	0	0	4
10:00 PM	1	0	0	2	1	0	0	0	0	0	0	0	0	0	0	0	0	4
11:00 PM	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Total	10	22	52	102	68	18	1	0	0	0	0	0	0	0	0	0	0	273
Percent	3.7%	8.1%	19.0%	37.4%	24.9%	6.6%	0.4%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	

Note: Average only considered on days with 24-hours of data.

Total Study Percentile Speed Summary			Total Study Speed Statistics		
50th Percentile (Median)	22.7	mph	Mean (Average) Speed	22.2	mph
85th Percentile	27.1	mph	10 mph Pace	17.6 - 27.6	mph
95th Percentile	30.2	mph	Percent in Pace	70.8	%

Location: Henderson Rd, Between Kelly Ln & .17 Miles N-O Kelly Ln
 Date Range: 2/22/2022 to 2/23/2022
 Site Code: YB3601

**Total Study Average
Southbound**

Time	Speed Range (mph)																	Total Volume
	0 - 10	10 - 15	15 - 20	20 - 25	25 - 30	30 - 35	35 - 40	40 - 45	45 - 50	50 - 55	55 - 60	60 - 65	65 - 70	70 - 75	75 - 80	80 - 85	85 +	
12:00 AM	1	1	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	3
1:00 AM	0	0	1	0	0	1	0	0	0	0	0	0	0	0	0	0	0	2
2:00 AM	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
3:00 AM	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	1
4:00 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
5:00 AM	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
6:00 AM	0	0	1	1	0	0	0	0	0	0	0	0	0	0	0	0	0	2
7:00 AM	0	1	3	4	2	0	1	0	0	0	0	0	0	0	0	0	0	11
8:00 AM	0	2	3	5	3	1	0	0	0	0	0	0	0	0	0	0	0	14
9:00 AM	0	1	1	6	2	1	0	0	0	0	0	0	0	0	0	0	0	11
10:00 AM	1	2	5	9	5	1	0	0	0	0	0	0	0	0	0	0	0	23
11:00 AM	1	2	2	6	5	1	0	0	0	0	0	0	0	0	0	0	0	17
12:00 PM	1	1	8	5	7	2	1	0	0	0	0	0	0	0	0	0	0	25
1:00 PM	3	0	4	9	6	0	2	0	0	0	0	0	0	0	0	0	0	24
2:00 PM	1	3	6	6	3	1	0	0	0	0	0	0	0	0	0	0	0	20
3:00 PM	0	1	7	5	6	1	0	0	0	0	0	0	0	0	0	0	0	20
4:00 PM	0	1	4	8	6	1	0	0	0	0	0	0	0	0	0	0	0	20
5:00 PM	0	4	2	10	5	1	0	0	0	0	0	0	0	0	0	0	0	22
6:00 PM	0	1	2	5	2	0	0	0	0	0	0	0	0	0	0	0	0	10
7:00 PM	0	1	3	2	2	0	0	0	0	0	0	0	0	0	0	0	0	8
8:00 PM	0	1	1	2	0	1	0	0	0	0	0	0	0	0	0	0	0	5
9:00 PM	0	1	2	2	1	0	0	0	0	0	0	0	0	0	0	0	0	6
10:00 PM	0	0	0	3	0	0	0	0	0	0	0	0	0	0	0	0	0	3
11:00 PM	1	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	2
Total	9	23	58	89	55	13	4	0	0	0	0	0	0	0	0	0	0	251
Percent	3.6%	9.2%	23.1%	35.5%	21.9%	5.2%	1.6%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	

Note: Average only considered on days with 24-hours of data.

Total Study Percentile Speed Summary			Total Study Speed Statistics		
50th Percentile (Median)	21.8	mph	Mean (Average) Speed	21.9	mph
85th Percentile	27.2	mph	10 mph Pace	17.4 - 27.4	mph
95th Percentile	30.6	mph	Percent in Pace	70.0	%