

Vehicle Classification Report Summary



Location: Deodar Way, B/W Santa Rosa Way & Keswick Dam Rd

Count Direction: Northbound / Southbound

Date Range: 4/3/2019 to 4/4/2019

Site Code: 66 - Y25401

	FHWA Vehicle Classification													Total Volume
	1	2	3	4	5	6	7	8	9	10	11	12	13	
Study Total														
Northbound	2	178	57	1	8	4	0	0	0	0	0	0	0	250
Percent	0.8%	71.2%	22.8%	0.4%	3.2%	1.6%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	100%
Southbound	5	197	58	0	14	0	0	0	0	0	0	0	0	274
Percent	1.8%	71.9%	21.2%	0.0%	5.1%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	100%
Total	7	375	115	1	22	4	0	0	0	0	0	0	0	524
Percent	1.3%	71.6%	21.9%	0.2%	4.2%	0.8%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	100%

FHWA Vehicle Classification	
Class 1 - Motorcycles	Class 8 - Four or Fewer Axle Single-Trailer Trucks
Class 2 - Passenger Cars	Class 9 - Five-Axle Single-Trailer Trucks
Class 3 - Other Two-Axle, Four-Tire Single Unit Vehicles	Class 10 - Six or More Axle Single-Trailer Trucks
Class 4 - Buses	Class 11 - Five or fewer Axle Multi-Trailer Trucks
Class 5 - Two-Axle, Six-Tire, Single-Unit Trucks	Class 12 - Six-Axle Multi-Trailer Trucks
Class 6 - Three-Axle Single-Unit Trucks	Class 13 - Seven or More Axle Multi-Trailer Trucks
Class 7 - Four or More Axle Single-Unit Trucks	

Location: Deodar Way, B/W Santa Rosa Way & Keswick Dam Rd
Date Range: 4/3/2019 to 4/4/2019
Site Code: 6 - Y25401



Wednesday, April 3, 2019
Northbound

Time	FHWA Vehicle Classification													Total Volume
	1	2	3	4	5	6	7	8	9	10	11	12	13	
12:00 AM	0	2	0	0	0	0	0	0	0	0	0	0	0	2
1:00 AM	0	0	1	0	0	0	0	0	0	0	0	0	0	1
2:00 AM	0	1	0	0	0	0	0	0	0	0	0	0	0	1
3:00 AM	0	3	0	0	0	0	0	0	0	0	0	0	0	3
4:00 AM	0	2	0	0	0	0	0	0	0	0	0	0	0	2
5:00 AM	0	1	0	0	0	0	0	0	0	0	0	0	0	1
6:00 AM	0	1	0	1	1	0	0	0	0	0	0	0	0	3
7:00 AM	0	8	2	0	0	0	0	0	0	0	0	0	0	10
8:00 AM	0	5	1	0	0	0	0	0	0	0	0	0	0	6
9:00 AM	0	4	0	0	0	0	0	0	0	0	0	0	0	4
10:00 AM	0	3	3	0	0	0	0	0	0	0	0	0	0	6
11:00 AM	0	5	3	0	0	0	0	0	0	0	0	0	0	8
12:00 PM	0	9	1	0	1	0	0	0	0	0	0	0	0	11
1:00 PM	0	5	3	0	0	0	0	0	0	0	0	0	0	8
2:00 PM	0	8	1	0	0	0	0	0	0	0	0	0	0	9
3:00 PM	0	6	3	0	1	0	0	0	0	0	0	0	0	10
4:00 PM	0	3	0	0	0	0	0	0	0	0	0	0	0	3
5:00 PM	0	5	3	0	0	1	0	0	0	0	0	0	0	9
6:00 PM	0	4	0	0	1	0	0	0	0	0	0	0	0	5
7:00 PM	0	3	4	0	0	0	0	0	0	0	0	0	0	7
8:00 PM	0	3	3	0	0	0	0	0	0	0	0	0	0	6
9:00 PM	0	3	1	0	0	0	0	0	0	0	0	0	0	4
10:00 PM	0	4	0	0	0	0	0	0	0	0	0	0	0	4
11:00 PM	0	1	0	0	0	0	0	0	0	0	0	0	0	1
Total	0	89	29	1	4	1	0	0	0	0	0	0	0	124
Percent	0.0%	71.8%	23.4%	0.8%	3.2%	0.8%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	

Location: Deodar Way, B/W Santa Rosa Way & Keswick Dam Rd
Date Range: 4/3/2019 to 4/4/2019
Site Code: 6 - Y25401



Wednesday, April 3, 2019
Southbound

Time	FHWA Vehicle Classification													Total Volume
	1	2	3	4	5	6	7	8	9	10	11	12	13	
12:00 AM	0	1	0	0	0	0	0	0	0	0	0	0	0	1
1:00 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0
2:00 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0
3:00 AM	0	1	0	0	0	0	0	0	0	0	0	0	0	1
4:00 AM	0	2	0	0	0	0	0	0	0	0	0	0	0	2
5:00 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0
6:00 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0
7:00 AM	0	4	3	0	0	0	0	0	0	0	0	0	0	7
8:00 AM	0	3	1	0	0	0	0	0	0	0	0	0	0	4
9:00 AM	0	3	0	0	0	0	0	0	0	0	0	0	0	3
10:00 AM	0	4	0	0	0	0	0	0	0	0	0	0	0	4
11:00 AM	0	3	4	0	0	0	0	0	0	0	0	0	0	7
12:00 PM	1	7	2	0	1	0	0	0	0	0	0	0	0	11
1:00 PM	0	4	5	0	1	0	0	0	0	0	0	0	0	10
2:00 PM	0	8	3	0	0	0	0	0	0	0	0	0	0	11
3:00 PM	0	8	6	0	0	0	0	0	0	0	0	0	0	14
4:00 PM	0	6	3	0	0	0	0	0	0	0	0	0	0	9
5:00 PM	0	10	1	0	2	0	0	0	0	0	0	0	0	13
6:00 PM	0	7	0	0	0	0	0	0	0	0	0	0	0	7
7:00 PM	0	6	0	0	0	0	0	0	0	0	0	0	0	6
8:00 PM	0	3	4	0	0	0	0	0	0	0	0	0	0	7
9:00 PM	0	4	1	0	0	0	0	0	0	0	0	0	0	5
10:00 PM	0	6	0	0	0	0	0	0	0	0	0	0	0	6
11:00 PM	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Total	1	90	33	0	4	0	0	0	0	0	0	0	0	128
Percent	0.8%	70.3%	25.8%	0.0%	3.1%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	

Location: Deodar Way, B/W Santa Rosa Way & Keswick Dam Rd
Date Range: 4/3/2019 to 4/4/2019
Site Code: 6 - Y25401



Thursday, April 4, 2019
Northbound

Time	FHWA Vehicle Classification													Total Volume
	1	2	3	4	5	6	7	8	9	10	11	12	13	
12:00 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0
1:00 AM	0	0	1	0	0	0	0	0	0	0	0	0	0	1
2:00 AM	0	1	0	0	0	0	0	0	0	0	0	0	0	1
3:00 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0
4:00 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0
5:00 AM	0	2	0	0	0	0	0	0	0	0	0	0	0	2
6:00 AM	0	2	1	0	0	0	0	0	0	0	0	0	0	3
7:00 AM	0	7	2	0	0	0	0	0	0	0	0	0	0	9
8:00 AM	0	3	1	0	0	0	0	0	0	0	0	0	0	4
9:00 AM	0	4	0	0	1	0	0	0	0	0	0	0	0	5
10:00 AM	0	6	2	0	0	0	0	0	0	0	0	0	0	8
11:00 AM	1	3	1	0	0	0	0	0	0	0	0	0	0	5
12:00 PM	0	3	1	0	1	0	0	0	0	0	0	0	0	5
1:00 PM	0	8	2	0	0	1	0	0	0	0	0	0	0	11
2:00 PM	0	13	2	0	1	2	0	0	0	0	0	0	0	18
3:00 PM	0	12	3	0	1	0	0	0	0	0	0	0	0	16
4:00 PM	0	3	1	0	0	0	0	0	0	0	0	0	0	4
5:00 PM	1	5	5	0	0	0	0	0	0	0	0	0	0	11
6:00 PM	0	5	0	0	0	0	0	0	0	0	0	0	0	5
7:00 PM	0	3	3	0	0	0	0	0	0	0	0	0	0	6
8:00 PM	0	5	1	0	0	0	0	0	0	0	0	0	0	6
9:00 PM	0	3	1	0	0	0	0	0	0	0	0	0	0	4
10:00 PM	0	1	1	0	0	0	0	0	0	0	0	0	0	2
11:00 PM	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Total	2	89	28	0	4	3	0	0	0	0	0	0	0	126
Percent	1.6%	70.6%	22.2%	0.0%	3.2%	2.4%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	

Location: Deodar Way, B/W Santa Rosa Way & Keswick Dam Rd
Date Range: 4/3/2019 to 4/4/2019
Site Code: 6 - Y25401



Thursday, April 4, 2019
Southbound

Time	FHWA Vehicle Classification													Total Volume
	1	2	3	4	5	6	7	8	9	10	11	12	13	
12:00 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0
1:00 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0
2:00 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0
3:00 AM	0	0	1	0	0	0	0	0	0	0	0	0	0	1
4:00 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0
5:00 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0
6:00 AM	0	1	0	0	0	0	0	0	0	0	0	0	0	1
7:00 AM	0	4	1	0	0	0	0	0	0	0	0	0	0	5
8:00 AM	0	6	2	0	0	0	0	0	0	0	0	0	0	8
9:00 AM	0	1	2	0	1	0	0	0	0	0	0	0	0	4
10:00 AM	0	3	0	0	0	0	0	0	0	0	0	0	0	3
11:00 AM	0	6	2	0	0	0	0	0	0	0	0	0	0	8
12:00 PM	0	9	4	0	0	0	0	0	0	0	0	0	0	13
1:00 PM	1	11	1	0	1	0	0	0	0	0	0	0	0	14
2:00 PM	2	18	2	0	4	0	0	0	0	0	0	0	0	26
3:00 PM	0	12	1	0	1	0	0	0	0	0	0	0	0	14
4:00 PM	1	5	3	0	0	0	0	0	0	0	0	0	0	9
5:00 PM	0	7	3	0	1	0	0	0	0	0	0	0	0	11
6:00 PM	0	10	1	0	0	0	0	0	0	0	0	0	0	11
7:00 PM	0	2	0	0	0	0	0	0	0	0	0	0	0	2
8:00 PM	0	4	1	0	0	0	0	0	0	0	0	0	0	5
9:00 PM	0	4	1	0	0	0	0	0	0	0	0	0	0	5
10:00 PM	0	3	0	0	2	0	0	0	0	0	0	0	0	5
11:00 PM	0	1	0	0	0	0	0	0	0	0	0	0	0	1
Total	4	107	25	0	10	0	0	0	0	0	0	0	0	146
Percent	2.7%	73.3%	17.1%	0.0%	6.8%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	

Location: Deodar Way, B/W Santa Rosa Way & Keswick Dam Rd
Date Range: 4/3/2019 to 4/4/2019
Site Code: 6 - Y25401

Total Study Average
Northbound

Time	FHWA Vehicle Classification													Total Volume
	1	2	3	4	5	6	7	8	9	10	11	12	13	
12:00 AM	0	1	0	0	0	0	0	0	0	0	0	0	0	1
1:00 AM	0	0	1	0	0	0	0	0	0	0	0	0	0	1
2:00 AM	0	1	0	0	0	0	0	0	0	0	0	0	0	1
3:00 AM	0	2	0	0	0	0	0	0	0	0	0	0	0	2
4:00 AM	0	1	0	0	0	0	0	0	0	0	0	0	0	1
5:00 AM	0	2	0	0	0	0	0	0	0	0	0	0	0	2
6:00 AM	0	2	1	1	1	0	0	0	0	0	0	0	0	5
7:00 AM	0	8	2	0	0	0	0	0	0	0	0	0	0	10
8:00 AM	0	4	1	0	0	0	0	0	0	0	0	0	0	5
9:00 AM	0	4	0	0	1	0	0	0	0	0	0	0	0	5
10:00 AM	0	5	3	0	0	0	0	0	0	0	0	0	0	8
11:00 AM	1	4	2	0	0	0	0	0	0	0	0	0	0	7
12:00 PM	0	6	1	0	1	0	0	0	0	0	0	0	0	8
1:00 PM	0	7	3	0	0	1	0	0	0	0	0	0	0	11
2:00 PM	0	11	2	0	1	1	0	0	0	0	0	0	0	15
3:00 PM	0	9	3	0	1	0	0	0	0	0	0	0	0	13
4:00 PM	0	3	1	0	0	0	0	0	0	0	0	0	0	4
5:00 PM	1	5	4	0	0	1	0	0	0	0	0	0	0	11
6:00 PM	0	5	0	0	1	0	0	0	0	0	0	0	0	6
7:00 PM	0	3	4	0	0	0	0	0	0	0	0	0	0	7
8:00 PM	0	4	2	0	0	0	0	0	0	0	0	0	0	6
9:00 PM	0	3	1	0	0	0	0	0	0	0	0	0	0	4
10:00 PM	0	3	1	0	0	0	0	0	0	0	0	0	0	4
11:00 PM	0	1	0	0	0	0	0	0	0	0	0	0	0	1
Total	2	94	32	1	6	3	0	0	0	0	0	0	0	138
Percent	1.4%	68.1%	23.2%	0.7%	4.3%	2.2%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	

Note: Average only considered on days with 24-hours of data.

Location: Deodar Way, B/W Santa Rosa Way & Keswick Dam Rd
Date Range: 4/3/2019 to 4/4/2019
Site Code: 6 - Y25401

Total Study Average
Southbound

Time	FHWA Vehicle Classification													Total Volume
	1	2	3	4	5	6	7	8	9	10	11	12	13	
12:00 AM	0	1	0	0	0	0	0	0	0	0	0	0	0	1
1:00 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0
2:00 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0
3:00 AM	0	1	1	0	0	0	0	0	0	0	0	0	0	2
4:00 AM	0	1	0	0	0	0	0	0	0	0	0	0	0	1
5:00 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0
6:00 AM	0	1	0	0	0	0	0	0	0	0	0	0	0	1
7:00 AM	0	4	2	0	0	0	0	0	0	0	0	0	0	6
8:00 AM	0	5	2	0	0	0	0	0	0	0	0	0	0	7
9:00 AM	0	2	1	0	1	0	0	0	0	0	0	0	0	4
10:00 AM	0	4	0	0	0	0	0	0	0	0	0	0	0	4
11:00 AM	0	5	3	0	0	0	0	0	0	0	0	0	0	8
12:00 PM	1	8	3	0	1	0	0	0	0	0	0	0	0	13
1:00 PM	1	8	3	0	1	0	0	0	0	0	0	0	0	13
2:00 PM	1	13	3	0	2	0	0	0	0	0	0	0	0	19
3:00 PM	0	10	4	0	1	0	0	0	0	0	0	0	0	15
4:00 PM	1	6	3	0	0	0	0	0	0	0	0	0	0	10
5:00 PM	0	9	2	0	2	0	0	0	0	0	0	0	0	13
6:00 PM	0	9	1	0	0	0	0	0	0	0	0	0	0	10
7:00 PM	0	4	0	0	0	0	0	0	0	0	0	0	0	4
8:00 PM	0	4	3	0	0	0	0	0	0	0	0	0	0	7
9:00 PM	0	4	1	0	0	0	0	0	0	0	0	0	0	5
10:00 PM	0	5	0	0	1	0	0	0	0	0	0	0	0	6
11:00 PM	0	1	0	0	0	0	0	0	0	0	0	0	0	1
Total	4	105	32	0	9	0	0	0	0	0	0	0	0	150
Percent	2.7%	70.0%	21.3%	0.0%	6.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	

Note: Average only considered on days with 24-hours of data.

Location: Deodar Way, B/W Santa Rosa Way & Keswick Dam Rd
Date Range: 4/3/2019 to 4/4/2019
Site Code: 6 - Y25401



**3-Day (Tuesday - Thursday) Average
 Northbound**

Time	FHWA Vehicle Classification													Total Volume
	1	2	3	4	5	6	7	8	9	10	11	12	13	
12:00 AM	0	1	0	0	0	0	0	0	0	0	0	0	0	1
1:00 AM	0	0	1	0	0	0	0	0	0	0	0	0	0	1
2:00 AM	0	1	0	0	0	0	0	0	0	0	0	0	0	1
3:00 AM	0	2	0	0	0	0	0	0	0	0	0	0	0	2
4:00 AM	0	1	0	0	0	0	0	0	0	0	0	0	0	1
5:00 AM	0	2	0	0	0	0	0	0	0	0	0	0	0	2
6:00 AM	0	2	1	1	1	0	0	0	0	0	0	0	0	5
7:00 AM	0	8	2	0	0	0	0	0	0	0	0	0	0	10
8:00 AM	0	4	1	0	0	0	0	0	0	0	0	0	0	5
9:00 AM	0	4	0	0	1	0	0	0	0	0	0	0	0	5
10:00 AM	0	5	3	0	0	0	0	0	0	0	0	0	0	8
11:00 AM	1	4	2	0	0	0	0	0	0	0	0	0	0	7
12:00 PM	0	6	1	0	1	0	0	0	0	0	0	0	0	8
1:00 PM	0	7	3	0	0	1	0	0	0	0	0	0	0	11
2:00 PM	0	11	2	0	1	1	0	0	0	0	0	0	0	15
3:00 PM	0	9	3	0	1	0	0	0	0	0	0	0	0	13
4:00 PM	0	3	1	0	0	0	0	0	0	0	0	0	0	4
5:00 PM	1	5	4	0	0	1	0	0	0	0	0	0	0	11
6:00 PM	0	5	0	0	1	0	0	0	0	0	0	0	0	6
7:00 PM	0	3	4	0	0	0	0	0	0	0	0	0	0	7
8:00 PM	0	4	2	0	0	0	0	0	0	0	0	0	0	6
9:00 PM	0	3	1	0	0	0	0	0	0	0	0	0	0	4
10:00 PM	0	3	1	0	0	0	0	0	0	0	0	0	0	4
11:00 PM	0	1	0	0	0	0	0	0	0	0	0	0	0	1
Total	2	94	32	1	6	3	0	0	0	0	0	0	0	138
Percent	1.4%	68.1%	23.2%	0.7%	4.3%	2.2%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	

Location: Deodar Way, B/W Santa Rosa Way & Keswick Dam Rd
Date Range: 4/3/2019 to 4/4/2019
Site Code: 6 - Y25401

3-Day (Tuesday - Thursday) Average
Southbound

Time	FHWA Vehicle Classification													Total Volume
	1	2	3	4	5	6	7	8	9	10	11	12	13	
12:00 AM	0	1	0	0	0	0	0	0	0	0	0	0	0	1
1:00 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0
2:00 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0
3:00 AM	0	1	1	0	0	0	0	0	0	0	0	0	0	2
4:00 AM	0	1	0	0	0	0	0	0	0	0	0	0	0	1
5:00 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0
6:00 AM	0	1	0	0	0	0	0	0	0	0	0	0	0	1
7:00 AM	0	4	2	0	0	0	0	0	0	0	0	0	0	6
8:00 AM	0	5	2	0	0	0	0	0	0	0	0	0	0	7
9:00 AM	0	2	1	0	1	0	0	0	0	0	0	0	0	4
10:00 AM	0	4	0	0	0	0	0	0	0	0	0	0	0	4
11:00 AM	0	5	3	0	0	0	0	0	0	0	0	0	0	8
12:00 PM	1	8	3	0	1	0	0	0	0	0	0	0	0	13
1:00 PM	1	8	3	0	1	0	0	0	0	0	0	0	0	13
2:00 PM	1	13	3	0	2	0	0	0	0	0	0	0	0	19
3:00 PM	0	10	4	0	1	0	0	0	0	0	0	0	0	15
4:00 PM	1	6	3	0	0	0	0	0	0	0	0	0	0	10
5:00 PM	0	9	2	0	2	0	0	0	0	0	0	0	0	13
6:00 PM	0	9	1	0	0	0	0	0	0	0	0	0	0	10
7:00 PM	0	4	0	0	0	0	0	0	0	0	0	0	0	4
8:00 PM	0	4	3	0	0	0	0	0	0	0	0	0	0	7
9:00 PM	0	4	1	0	0	0	0	0	0	0	0	0	0	5
10:00 PM	0	5	0	0	1	0	0	0	0	0	0	0	0	6
11:00 PM	0	1	0	0	0	0	0	0	0	0	0	0	0	1
Total	4	105	32	0	9	0	0	0	0	0	0	0	0	150
Percent	2.7%	70.0%	21.3%	0.0%	6.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	